

<b>4</b>	<b>BILL No.4</b>				
	<b>SENOANE CLINIC</b>				
	The UPS system consist of 2x 12kVA Riello UPS. The UPS are in bypass mode both UPS require a MAJOR service. The service will include the following:				
<b>Item</b>	<b>Description</b>	<b>Unit</b>	<b>Qty</b>	<b>Rate</b>	<b>Amount</b>
4.1	<b>UPS MAJOR service</b>				
4.1.1	Download event History	no.	2		
4.1.2	Upgrade firmware to latest revision	no.	2		
4.1.3	Cleaning of the UPSs	no.	2		
4.2	<b>Replacement of batteries</b>				
4.2.1	Test, Supply, deliver, install new VRLA 12V, 7Ah batteries complete with battery enclosure for both UPSs	no.	2		
4.3	<b>Commissioning</b>				
4.3.1	Commissioning the two systems complete in the presence of the Engineer	sum	1		
4.4	<b>Miscellaneous</b>				
4.4.1	Provide Red top (shaved earth) plug top leads	No.	20		
4.4.2	Remove the temporary red marking labels and replace it with permanent trefolite labelling	No.	250		
4.4.3	Neaten the IT cabling and install them in a trunking/ power skirting and clean all the dust in the cabinet	sum	1		
4.4	Test and confirm the UPS output DB circuitry and issue a CoC. This must include the following labels				
4.4.1	Sockets labelling	sum	1		
4.4.2	DB Labelling	sum	1		
4.4.3	Legend card	sum	1		
4.4.4	CoC ( <b>Only for UPS Output DB</b> )	no.	1		
4.5	Supply a Service record book with two carbon copies	no.	1		
4.6	Service of the Air Condition Unit	Sum	1		
4.7	Professional fees ( 15%, exclude P&Gs and Contingency)	%	0.15		
	<b>Total for Bill No 4: Protea Glen Clinic Forward to Bill of Quantities Summary Page</b>				