

<b>BILL No. 3:</b>
<b>GREEN VILLAGE CLINIC</b>
<b>The UPS system consist of 2x 12kVA Riello UPS. The UPS are in bypass mode both UPS require a MAJOR service. The service will include the following:</b>

Item	Description	Unit	Qty	Rate	Amount
3.1	<b>UPS MAJOR service</b>				
3.1.1	Download event History	no.	2		
3.1.2	Upgrade firmware to latest revision	No.	2		
3.1.3	Cleaning of the UPSs	No.	2		
3.2	<b>Replacement of batteries</b>				
3.2.1	Test,Supply, deliver, install new VRLA 12V, 7Ah batteries complete with battery enclosure for both UPSs	No.	2		
3.3	<b>Commissioning</b>				
3.3.1	Commissioning the two systems complete in the presence of the Engineer	sum	1		
3.4	<b>Miscellaneous</b>				
3.4.1	Clean the room and make it neat. All IT cables to be neatly packed.	Sum	1		
3.5	Test and confirm the UPS output DB circuitry and issue a CoC. This must include the following labels				
3.5.1	Sockets labelling	Sum	1		
3.5.2	DB Labelling	Sum	1		
3.5.3	Legend card	Sum	1		
3.5.4	CoC ( <b>Only for UPS Output DB</b> )	No.	1		
3.6	Supply a Service record book with two carbon copies	No.	1		
3.7	Service of the Air Condition Unit	Sum	1		
3.8	Provide Red top (shaved earth) plug top leads	No.	20		
3.9	Professional fees ( 15%, exclude P&Gs and Contingency)	%	0.15		
<b>Total for Bill No 3: Green Village Clinic Forward to Bill of Quantities Summary Page</b>					