REFURBISHMENT OF REMAINING EXTENT OF PORTION 48 OF THE FARM KLIPFONTEIN 58-IR: PATERSON PARK BOWLING CLUB.

SCOPE OF WORK	SIZE / QUANTITY	PRICE
Refurbishment of entire roof	101.9 M ²	
Painting of entire club house	101.9 m ²	
	Height – 6M	
Replacement or Ceiling (Entire Building)	19M	
Varanda - Installation of Ceiling - Installation of roof fisher-boards - Installation of gutters	20 X 4.5M	
Boardroom - Painting of entire wall - Replacement of ceiling	30.3 X 3 8 X 7.1	
Main Hall - Repair concrete roof slab - Replacement of ceiling	25 X12.7 X 3(wall)	
Main Gate - Supply and installation of the gate with electric motor	10M	

Supply and install sheets Clearview fence	3 sheets X 3m	
Supply and install solar lights batteries (24 Volts)	24 x 46	
Kitchen 1		
 Replacement of Ceiling Replacement of taps Replacement of cupboards and handles Repair of widows Installation of a door Replacement of missing tiles Skirting 		
Kitchen 2		
 Replacement of Ceiling Replacement of taps Replacement of cupboards and handles Repair of widows Installation of a door 		
Kitchen 3		
 Replacement of Ceiling Replacement of taps Replacement of cupboards and handles Repair of widows Installation of a door Replacement of tiles Skirting 		

_	
Female Toilets - Repair of ceiling - Replacement of taps - Repair of window - Replacement of missing tiles - Skirting - Installation of electronic hand dryer - Repair of flush toilets	
Male Toilets - Replacement of urinal mechanism - Repair of ceiling - Replacement of taps - Repair of window - Replacement of missing tiles - Installation of electronic hand dryer - Repair of flush toilets - Skirting	
Storage room - Replacement of ceiling - Replacement of doors	
Office - Repair of window - Painting of entire wall - Skirting	
Replacement all doors including main glass door Replacement of door handles and lock mechanisms	