

At long last, Rissik Street post office will get its revamp

Vandalised, burnt, the clock tower stripped; now it'll be restored

SAMANTHA HARTSHORNE

RESTORATION work has finally begun on one of Joburg's coonic inner-city buildings.

Having endured two fires, vandalism and neglect over the lexistic Street post office will be restored to its former glory the time it marks its 120th year next year.

the time it marks its 120th year next year.

Situated in the historic trio that includes the town hall and the city library, work has begun to renovate the building and revive it for potential event boxting.

and the city in any, won assegue to removate the building another than the city of the cit

Street.
"The frontage has always been Rissik Street but we want to have a more exciting and contemporary-style entrance," she said.



GUTTED: Fire and emergency services members watch the post office burn in 2009. The building was abandoned at the time. After that, promises were made and broken to restore it, now, they are a reality.

drawings I Creates the said.

The City of Joburg is the registered owner of the Rissik Street post office and made the funding available.

"This funding is to prepare the building for construction

MCIUSE: KARRI SANDEON
to make it safer for further
work and interim use. The
short-term intervention will
be erected within the existing
structure to ensure structural
integrity; Said Botes.
Micra fire in 200, Riom
of father a fire in 200, Riom
of repair the roof and halt the
decline and structural docay.
Hiophe said the first phase
should be completed by the end
of the year, when the interior
work would be finished, including the strengthening of the
columns and trusses to allow
for future renovations.

JPC said once fully

developed into a multi-use space, the stately building space, the stately building could offer a variety of venues. "This interim phase talks to the north and south wing where we'll be putting up a steel structure to reinforce the building and then starting with the external façade later," said Botes.

JPC said the roll-out of the work would depend on the location of the budget but onlookers would really only notice the upgrades when the outside façade was given attention.

outside tagade was given attention.

The final phases, predicted
to cost a further R100m, will
include installing a clock simindependent of the cost of the co



for launches, music concerts or fashion events."

The cost of repair will include, among others, reinforing the basement foundations, securing the timber flooring and removing and reinstating the roof to install steelwork.

"I am delighted something is happening at last, but I was told it would be limited to the steel skeleton to be inserted into the building to hold any future infill." said Flo Bird of the Parktown and Westelff Heritage Association.

External scaffolding, the reinforcement of concrete beautiful and the result of the reinforcement of concrete beautiful and the result of the result

style", which features an exaggerated central tower and tall windows. The façade on Rissik Street and the original market THE Post Office was first built in

1897. The original design, by Sytze Wierda, features painted plaster accents and red facebrick with Wierda also worked on the

Raadsaal (1890) and the Palace of Justice (1897), both in Pretoria. The style of the building is

also being done.

A large chunk of the money will be spent on erecting scaffolding to allow access to the roof and creating an 11m structural frame inside the building. Reinforced concrete bases and concrete columns on both

just three years after being built and a fourth story was added.

square includes two ornamental roofed elevated towers and a

building was deemed too small

central turret. Initially three storeys high, the

dent Street sides will improve accessibility. The clock tower's copper sheeting as well as the clock itself have, over the years, been stripped. In 2002, the bells were stolen

PRIJUE: BANNET COLLECTION
and inside, handles and light
fittings have all been stolen.
Inside, all that is left of the
suspended wooden flooring is
the steel base, revealing the
sament area below Fire damage is extensive.
"Externally, the condition
of the building appears worse
than it actually is. Besides
the problem of distintegrating
plasterwork and sandstone
mornings of the steel steel the
plasterwork and sandstone
mornings of the steel the
restormer of the steel
plasterwork and sandstone
mornings are capable restorer
would not be able to repair,
said heritage consultant
Johann Bruwer in a heritage
assessment survey dated 2002.
Plans have been submitted
to the heritage council and JPC
has applied for permits.
Detailed plans include the
revamping of the park area
and contact has been made
with Johung City Parks and
Zoo regarding the extensions.



WHAT REMAINS: The interior of the post office after the fire

